

1000028031

County Lyon
Quad
Quad ID

MINNESOTA DEPARTMENT OF HEALTH
WELL AND BORING REPORT
Minnesota Statutes Chapter 1031

Entry Date07/05/2022
Update Date07/05/2022
Received Date

Well Name ERICKSON,	Township 111	Range 42	Dir Section W 35	Subsection BAB	Well Depth null	Depth Completed null	Date Well Completed 00/00/1951					
Elevation	Elev. Method				Drill Method	Drill Fluid						
Address C/W LYND MN					Use domestic	Status Unknown						
					Well Hydrofractured?	Yes ☐	No ☐	From	To			
Stratigraphy Information					Casing Type	Joint						
					Drive Shoe?	Yes ☐	No ☐	Above/Below				
					Casing Diameter	Weight						
					5 in. To	ft.	lbs./ft.					
					Open Hole				From	ft.	To	ft.
					Screen?	☐	Type	Make				
					Static Water Level							
					Pumping Level (below land surface)							
					ft.				hrs.	Pumping at	g.p.m.	
					Wellhead Completion							
Pitless adapter manufacturer					Model							
☐ Casing Protection					☐ 12 in. above grade							
☐ At-grade (Environmental Wells and Borings ONLY)												
Grouting Information					Well Grouted?	☐ Yes	☐ No	☒ Not Specified				
Nearest Known Source of Contamination												
feet					Direction		Type					
Well disinfected upon completion?					☐ Yes	☐ No						
Pump					☐ Not Installed	Date Installed						
Manufacturer's name												
Model Number					HP	0.5	Volt					
Length of drop pipe					ft	Capacity	g.p.	Typ	Piston			
Abandoned												
Does property have any not in use and not sealed well(s)?					☐ Yes	☐ No						
Variance												
Was a variance granted from the MDH for this well?					☐ Yes	☐ No						
Miscellaneous												
First Bedrock					Aquifer							
Last Strat					Depth to Bedrock		ft					
Located by												
Locate Method												
System					UTM - NAD83, Zone 15, Meters		X	Y				
Unique Number Verification					Input Date							
Angled Drill Hole												
Well Contractor												
Licensee Business					Lic. or Reg. No.		MARTIN, O. Name of Driller					