

Minnesota Unique Well Number

833168

CountyBlue Earth

Quad

Quad ID

MINNESOTA DEPARTMENT OF HEALTH

WELL AND BORING REPORT

Minnesota Statutes Chapter 1031

Entry Date06/29/2020

Update Date02/18/2021

Received Date02/05/2020

Well Name	Township	Range	Dir	Section	Subsection	Well Depth	Depth Completed	Date Well Completed	
NUYTEN, MATT 108		29	W	3	CCD	153 ft.	153 ft.	11/22/2019	
Elevation	Elev. Method					Drill Method	Non-specified Rotary	Drill Fluid	Bentonite
Address						Use	domestic	Status	Active
Well						48976 222ND ST LAKE CRYSTAL MN			
Contact						130 CHARLOTTE DR LAKE CRYSTAL MN 56055			
Stratigraphy Information									
Geological Material	From	To (ft.)	Color	Hardness					
SOIL	0	2	BLACK	SOFT					
CLAY SANDY	2	17	YELLOW	SOFT					
CLAY STICKY	17	47	BLUE	SOFT					
CLAY MINIOR SAND	47	93	GRAY	HARD					
MEDIUM SAND	93	107	GRAY	SOFT					
FIRM CLAY	107	130	GRAY						
SAND MEDIUM FINE	130	153	TAN	SFT-HRD					
FIRM CLAY	153	153	BROWN						
Well Hydrofractured? Yes ☐ No ☒ From To									
Casing Type Single casing Joint Welded									
Drive Shoe? Yes ☐ No ☒ Above/Below									
Casing Diameter Weight Hole Diameter									
5 in. To 143 ft. lbs./ft. 8 in. To 153 ft.									
Open Hole From ft. To ft.									
Screen? ☒ Type telescoping Make JOHNSON									
Diameter Slot/Gauze Length Set									
5 in. 15 13 ft. 143 ft. 153 ft.									
Static Water Level									
86 ft. land surface Measure 07/15/2019									
Pumping Level (below land surface)									
ft. hrs. Pumping at 60 g.p.m.									
Wellhead Completion									
Pitless adapter manufacturer MAASS Model									
☐ Casing Protection ☐ 12 in. above grade									
☐ At-grade (Environmental Wells and Borings ONLY)									
Grouting Information Well Grouted? ☒ Yes ☐ No ☐ Not Specified									
Material Amount From To									
bentonite 7 Sacks 0 ft. 100 ft.									
cuttings 100 ft. ft.									
Nearest Known Source of Contamination									
73 feet South Direction Septic tank/drain field Type									
Well disinfected upon completion? ☒ Yes ☐ No									
Pump ☐ Not Installed Date Installed									
Manufacturer's name SCHAEFER									
Model Number HP 0.75 Volt									
Length of drop pipe 12 ft Capacity 10 g.p. Typ Submersible									
Abandoned									
Does property have any not in use and not sealed well(s)? ☐ Yes ☒ No									
Variance									
Was a variance granted from the MDH for this well? ☐ Yes ☒ No									
Miscellaneous									
First Bedrock Aquifer									
Last Strat Depth to Bedrock ft									
Located by									
Locate Method									
System UTM - NAD83, Zone 15, Meters X Y									
Unique Number Verification Input Date									
Angled Drill Hole									
Well Contractor									
Searles Well Drilling, Inc. 1493 KUCK, TROY									
Licensee Business Lic. or Reg. No. Name of Driller									
Remarks									
RECEIVED BY ENVIRONMENTAL SERVICES 01/15/2020									
ADDITIONAL DATA ADDED 07/07/2020									
ELEV. +/- 993									

Minnesota Well Index Report

833168

Printed on 08/13/2026
HE-01205-15